

sht1/17




Figure 1

sht2/17




Fig. 2

sht3/17




Fig.3

sht4/17




Fig.4

sht5/17




Fig.5

sht6/17

**Tank 12D**

Structure:	Demonstration Product Terminal-Tanks
Condition Grade:	E
Last Inspection Date:	4/17/2003
Paint System:	C2A

**Structure Overview:**

**Total Costs**

<b>Recommended Work</b>	<b>\$67,900.00</b>
Touch-Up	\$29,100.00
Refresh	\$38,800.00
Restore	\$0.00

**Structures**

Select a structure from the pull-down menu to view its elements.

Choose a Structure

**Reports**

- Coating System Performance
- Optimum Work Schedule
- Deferred Work
- Custom Report

Fig. 6

sht7/17

### Demonstration Product Terminal-Tanks

Priority:

☆☆☆

Average Grade:

A

Last Inspection Date:

### Structure Overview:

#### Total Costs

\$265,055.30

#### Recommended Work

\$265,055.30

Touch-Up

\$67,825.30

Refresh

\$95,890.00

Restore

\$101,340.00

#### Elements Menu

Select an element from this structure

Choose an Element

#### Structures Menu

Select a structure from the pull down below

Choose a Structure

#### Structure Level Reports

Summary Recommended Work

Recommended Work Report (1 Year Forecast)

Recommended Work Report (5 Year Forecast)

Cost of Deferring Work

Fig. 7

sht8/17

## Demonstration Enterprise

### Total Costs

#### Recomended Work

**\$265,055.30**

Touch-Up	\$67,825.30
Refresh	\$95,890.00
Restore	\$101,340.00

### Structure Menu

Select a structure from the pull-down below.

Choose a Structure 

### Enterprise Level Reports

Summary Recommended Work  
Recommended Work Report (1 Year Forecast)  
Recommended Work Report (3 Year Forecast)  
Cost of Deferring Work

Fig.8



sht9/17

## Summary Report

---

### Tank 8

Condition Grade:

Last Inspection Date:

Paint System:

### Total Costs

### Recommended Work

Touch-Up

Refresh

Restore

### Tank 12

Condition Grade:

Last Inspection Date:

Paint System:

### Total Costs

### Recommended Work

Touch-Up

Refresh

Restore

Fig.9

sht10/17

### Summary Report 1 Year Forcast

---

#### Tank 8

Condition Grade:

Last Inspection Date:

Paint System:

#### Total Costs

#### Recomended Work

Touch-Up

Refresh

Restore

---

#### Tank 12

Condition Grade:

Last Inspection Date:

Paint System:

#### Total Costs

#### Recomended Work

Touch-Up

Refresh

Restore

Fig.10

sht11/17

### Summary Report 3 Year Forecast

---

#### Tank 4

Condition Grade:

Last Inspection Date:

Paint System:

#### Total Costs

#### Recommended Work

Touch-Up

Refresh

Restore

#### Tank 6

Condition Grade:

Last Inspection Date:

Paint System:

#### Total Costs

#### Recommended Work

Touch-Up

Refresh

Restore

Fig. 11

sht12/17

Elements		
SELECTED PHOTO	South Crossover	Visit
	Condition Grade:	A
	Total Area:	580
	Repair Area:	0%
SELECTED PHOTO	South Crossover	Visit
	Condition Grade:	A
	Total Area:	580
	Repair Area:	0%
SELECTED PHOTO	South Crossover	Visit
	Condition Grade:	A
	Total Area:	580
	Repair Area:	0%

Fig.12

sht13/17

## Coating System Performance Report

Structure:	Demonstrati
Element:	
Paint System:	
Performance:	
<hr/>	
Structure:	Demonstrati
Element:	
Paint System:	
Performance:	
<hr/>	
Structure:	Demonstrati
Element:	
Paint System:	
Performance:	8:

Fig.13

sht14/17

## Optimum Work Schedule Report

### Structure:

Next Year :      Tank 8  
                 Tank 12  
                 Tank 10

Within 3 Years:      Tank 4  
                 Tank 6

### Demonstration

Fig.14

sht15/17

### Completed Work Report

Structure: Demonstrati  
Budgeted Cost :  
Actual Cost :

Structure: Demonstrati  
Budgeted Cost :  
Actual Cost :

Structure: Demonstrati  
Budgeted Cost :  
Actual Cost :

Fig.15

sht16/17

## Summary Report 1 Year Forcast

---

### Tank 8

Condition Grade:

Last Inspection Date:

Paint System:

### Total Costs

### Recomended Work

Touch-Up

Refresh

Restore

### Tank 12

Condition Grade:

Last Inspection Date:

Paint System:

### Total Costs

### Recomended Work

Touch-Up

Refresh

Restore

Fig.16



sht17/17

## Summary Report 3 Year Forcast

---

### Tank 4

Condition Grade:

Last Inspection Date:

Paint System:

### Total Costs

### Recomended Work

Touch-Up

Refresh

Restore

### Tank 6

Condition Grade:

Last Inspection Date:

Paint System:

### Total Costs

### Recomended Work

Touch-Up

Refresh

Restore

Fig.17